

ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್‌ರವರ ಕಛೇರಿ
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ವಿಶೇಷ ವಿಭಾಗ, ಹುಣಸೂರು

ಕರ್ನಾಟಕ ಸರ್ಕಾರ



O/o The Executive Engineer
Public Works Department,
Special Division, Hunsur

Email-eehsr@kpwd.gov.in

PhNo.08222-251855/955

ಸಂ:ಕಾಇಂ:ಲೋಇ:ವಿವಿಹು/ಸು.ಪ್ರ.ಪತ್ರ/2022-23

3863

ದಿನಾಂಕ: 04-02-2023

ಇವರಿಗೆ:

ಮುಖ್ಯ ಉಪಾಧ್ಯಾಯಿನಿ
ಟ್ರೋ ಶೆಫರ್ಡ್ ಪಬ್ಲಿಕ್ ಶಾಲೆ,
ಶಾಂತಿಪುರ ,
ಹೆಚ್.ಡಿ.ಕೋಟೆ ಟೌನ್

ಮಾನ್ಯರೇ,

- ವಿಷಯ:- ಮೈಸೂರು ಜಿಲ್ಲೆ ಹೆಚ್.ಡಿ.ಕೋಟೆ ತಾಲ್ಲೂಕು , ಟ್ರೋ ಶೆಫರ್ಡ್ ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್
ಶಾಂತಿಪುರ ಟೌನ್ ಕಟ್ಟಡದ ಸುರಕ್ಷಿತ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.
ಉಲ್ಲೇಖ:- 1.ಸರ್ಕಾರದ ಆದೇಶ ಸಂ:ಲೋಇ:ಇ:59/ಬಿಇಬಿ/2019/ಡಿ: 06-05-2022
2.ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ,
ಉಪವಿಭಾಗ, ಹೆಚ್.ಡಿ.ಕೋಟೆ ಇವರ ಪತ್ರ ಸಂ:1013/ಡಿ:27-01-2023


-000-

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ ಹೆಚ್.ಡಿ.ಕೋಟೆ ತಾಲ್ಲೂಕು , ಟ್ರೋ ಶೆಫರ್ಡ್ ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್ ಶಾಂತಿಪುರ
ಟೌನ್ ಕಟ್ಟಡದ ಸುರಕ್ಷಿತ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಬೇಕಾಗಿ ಮುಖ್ಯೋಪಾಧ್ಯಾಯಿನಿ ಇವರು ಕೋರಿರುವ ಹಿನ್ನೆಲೆಯಲ್ಲಿ
ಮತ್ತು ಈ ಸಂಬಂಧ ಉಲ್ಲೇಖಿತ ಪತ್ರ (1)ರಲ್ಲಿ ಸರ್ಕಾರದ ಆದೇಶದಲ್ಲಿ ತಿಳಿಸಿರುವ ದಾಖಲಾತಿಗಳನ್ನು ಒದಗಿಸಿದ್ದು ಈ
ಸಂಬಂಧ ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷಿತ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ , ಉಪವಿಭಾಗ, ಹೆಚ್.ಡಿ.ಕೋಟೆ ಇವರು ಉಲ್ಲೇಖಿತ ಪತ್ರ (2)ರಲ್ಲಿ ಶಿಫಾರಸ್ಸು
ಮಾಡಿರುತ್ತಾರೆ.

ಮುಂದುವರೆದು ಉಲ್ಲೇಖ ಪತ್ರ (1)ರ ಸರ್ಕಾರಿ ಆದೇಶದನ್ವಯ ನಗರ ಪ್ರದೇಶದಲ್ಲಿರುವ ಶಾಲೆಗೆ ರೂ.5000/-
(ಐದು ಸಾವಿರ ರೂಪಾಯಿಗಳು ಮಾತ್ರ) ಗಳನ್ನು ರಶೀದಿ ನಂ.65079/ ದಿನಾಂಕ:02-02-2023 ರಲ್ಲಿ ಪಾವತಿಸಿದ್ದು ಸದರಿ
ಕಟ್ಟಡವು ಬಳಕೆಗೆ ಯೋಗ್ಯವಿದೆ ಎಂದು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ,
ಉಪವಿಭಾಗ, ಹೆಚ್.ಡಿ.ಕೋಟೆ ಇವರು ಶಿಫಾರಸ್ಸು ಮಾಡಿರುವ ಹಿನ್ನೆಲೆಯಲ್ಲಿ ಸದರಿ ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿದೆ ಎಂದು
ದೃಢೀಕರಿಸಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,
ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ವಿಶೇಷ ವಿಭಾಗ,
ಹುಣಸೂರು.


HEAD MASTER
True Shepherd Public School
S. G. H. Road, H. D. Kote Taluk
Mysore District


Managing Trustee
True Shepherd Public School
Heggadadevanakote-571 114
Mysore District

On receipt of the General Information of the Building along with the available documents, the concerned certificate issuing authority of PWD shall carry out the visual inspection for the Structural Stability of the Building as below

Date of Inspection: ...17/01/2023


Sl.No	Requirement	Result	Remarks
1	Observed any deviation of approval plan structural design in the construction of buildings (If the documents are enclosed)	No	
2	Visually observed any structural cracks (Cracks in RCC Beams, Columns, Walls, Slabs, Spalling of Concrete, Sagging of Beams or Slabs, Tilting of Columns or RC Frames (Out of Plumb))	No	
3	Visually observed any moisture / dampness in the Building	No	
4	Visually observed any temporary arrangement for the distressed members	No	
5	Visually observed any non-structural cracks	No	
6	Any non-structural failing hazards including ceilings, partitions, curtain walls, parapets, fixtures and other non-structural building elements found.	No	
7	Any leakages in terrace, toilets, plumbing lines, drainage lines and overhead tanks are found	No	
8	Any exposure of reinforcement is found and adequacy of clear cover	No	
9	Results of the Non-destructive test like Rebound Hammer Test / Ultrasonic Pulse Velocity Test / Profometer for Rebars (Combination of any Two) is Satisfactory?	Not Conducted	The Building is New and Less than 5 Years Old and do not warrant Non-Destructive Tests
10	Results of the Compressive Strength Test on Concrete Core is Satisfactory?		


Note: For Buildings aging less than 5 years, if the results are satisfactory based on the visual inspection and the available structural design and drawings are found correct, the non-destructive tests need not be performed.

Else or if needed, non-destructive test may be recommended

Condition Assessment of the Building and Recommendation:

The Building is Very Sound and Recommended for issuance of Structural Stability Certificate


Assistant Executive Engineer
PWD Sub-Division
Heggadadevanakote


Executive Engineer
PWD -Division
Hunsur

GOVT OF KARNATAKA

**Public Works Department
Office of the Executive Enngineer
Hunsur – 571105**


No: EE/PWD/HUN/Structural Stability Certificate/2022-23/


^{38/3} Date :


04.02.2023.


Structural Stability Certificate

This is to certify that **True Shepherd Public School**, 198, Shantipura, Heggadadevanakote – 571114, Mysore District is a RCC Framed Structure Building consisting of Ground Plus Three (3) Floors. The Plan was approved by Town Planning Department, Mysore and Gram Panchayat, Chakkodanahalli, Heggadadevanakote. The School Building was inspected and the Building is constructed as per the norms of 'National Building Code'. The Building is very sound and safe to run the school. Further, the school authorities have made all provisions for the safety of the Students and Staff.


**Assistant Executive Engineer
PWD Sub-Division
Heggadadevanakote**


**Executive Engineer
PWD -Division
Hunsur**


**HEAD MISTRESS
True Shepherd Public School
Shantipura, H.D. Kote, H.D. Kote Taluk
Mysore District**


**Manager
True Shepherd Public School
Heggadadevanakote-571114
Mysore District**